

600/5800转频终端 & 5.8G PRU - 错误 #1017

通过dev配置频点后，概率性产生读取频点卡住的情况。

2023-01-10 03:43 - 战弋戈

[illegible]

busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?
busy1, check RU device ok?

历史记录

- #1 - 2023-01-09 19:47 - 高峰
- 类别 被设置为 3.5G_PRU
- 指派给 被设置为 匿名用户
- 优先级 从 普通 变更为 高
- 问题归属 PRU 已添加