

FirstCall - 错误 #2707

使用EVMT2板卡测试，接收不到数据，界面打印adrv9025_init失败

2025-01-15 11:16 - 杨晋

状态:	已关闭	开始日期:	2025-01-15
优先级:	普通	计划完成日期:	
指派给:	李明新	% 完成:	0%
类别:		预期时间:	0.00 小时
目标版本:		耗时:	0.00 小时
描述			
<pre>pin OK enable_jesd ApelWorkStep@ 1 adrv9025Device init ok! deframer_0: 204cStatus: 0, enableLane: F deframer_1: 204cStatus: 0, enableLane: 0 SUCESS: MCS Status 0x17 Tx calibration is done commonDev abort ERR RETURN: public/src/adi_adrv9025_cpu.c 1120 adi_adrv9025_CpuCmdStatusWait path 1&4 Rx ORX calibration is done ERR RETURN: private/src/adrv9025_bf_jesd_common.c 920 adrv9025_JesdCommonJtxTriggerSrstNBfSet commonDev abort ERR RETURN: public/src/adi_adrv9025_data_interface.c 3424 adi_adrv9025_SerializerReset ERROR: : adrv9025_init:2259 has failed. ApelWorkStep@ 2 root@driver:~/zaj/phy# cat /sys/class/hwmon/hwmon hwmon0/ hwmon1/ root@driver:~/zaj/phy# cat /sys/class/hwmon/hwmon0/ TsA_Alarm_threshold TsB_Hysteresis_threshold VmB_Alarm_threshold name subsystem/ uevent TsA_Hysteresis_threshold VmA_Alarm_threshold VmB_Hysteresis_threshold of_node/ TsB_Alarm_threshold VmA_Hysteresis_threshold device/ power/ root@driver:~/zaj/phy# cat /sys/class/hwmon/hwmon0/u ucp_temp_val ucp_vol_val uevent root@driver:~/zaj/phy# cat /sys/class/hwmon/hwmon0/ucp_temp_val 49680</pre>			
相关的问题:			
关联到 产品3.0平台 - 错误 #2690: 9025校准概率性不通过		挂起	2025-01-13

历史记录

#1 - 2025-01-15 16:11 - 杨晋

- 状态从 新建 变更为 进行中

#2 - 2025-01-15 16:12 - 杨晋

- 状态从 进行中 变更为 转测试

adrv9025_init失败概率性出现，后来好了

#3 - 2025-01-16 17:17 - 杨晋

- 指派给从 杨晋 变更为 李明新

#4 - 2025-01-16 18:08 - 杨晋

- 状态从 转测试 变更为 进行中

#5 - 2025-01-23 19:36 - 杨晋

- 关联到 错误 #2690: 9025校准概率性不通过 已添加

#6 - 2025-01-23 19:37 - 杨晋

- 状态从 进行中 变更为 已关闭

在2690问题单中继续跟踪

文件

