

3.0基站产品测试 - 错误 #4782

Rel_3.1.5_Pre1T2版本UE重建立异常

2026-01-23 16:40 - 郭 锁奇

状态:	进行中	开始日期:	2026-01-23
优先级:	一般	计划完成日期:	
指派给:	周 立伟	% 完成:	0%
类别:		预期时间:	0.00 小时
目标版本:		耗时:	0.00 小时
问题归属:	DU	目标解决问题版本:	Rel_3.1.5
发现问题版本:	Rel_3.1.5		
描述			
Rel_3.1.5_Pre1T2版本UE重建立流程不完整，缺少重配完成消息。			

历史记录

#1 - 2026-01-27 10:38 - 周 立伟

- 指派给 从 周 立伟 变更为 魏 幸幸

#2 - 2026-01-31 10:30 - 魏 幸幸

- 状态 从 新建 变更为 进行中

#3 - 2026-01-31 10:31 - 魏 幸幸

解决crnti泄露，重建立的UE msg4状态没有维护，导致重建立失败，已修复合入。

#4 - 2026-01-31 10:33 - 魏 幸幸

- 文件 屏幕截图 2026-01-31 103232.png 已添加

390 2026-01-29 09:27:05.901553 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x79ff6edd
394 2026-01-29 09:27:06.921572 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0xfb90ce08
398 2026-01-29 09:27:07.941534 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x575ce4b
402 2026-01-29 09:27:08.961536 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x87c135b8
406 2026-01-29 09:27:09.981517 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x127ceb35
412 2026-01-29 09:27:11.001546 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0xe400b05f9
418 2026-01-29 09:27:12.148035 192.168.62... 192.168.62.247 F1AP/NR RRC	InitialULRRCMessageTransfer, RRC Reestablishment Request
419 2026-01-29 09:27:12.149597 192.168.62... 192.168.62.247 F1AP/NR RRC	SACK (Ack=42, Arwid=1048576) , DLRRCMessageTransfer, RRC Reestablishment MAC=0x5e9eada0
420 2026-01-29 09:27:12.151066 192.168.62... 192.168.62.247 F1AP	SACK (Ack=17, Arwid=1048576) , UEContextModificationRequired
421 2026-01-29 09:27:12.151415 192.168.62... 192.168.62.247 F1AP	SACK (Ack=43, Arwid=1048576) , UEContextModificationConfirm
422 2026-01-29 09:27:12.207117 192.168.62... 192.168.62.247 F1AP/NR RRC	SACK (Ack=18, Arwid=1048576) , ULRRCMessageTransfer, RRC Reestablishment Complete MAC=0xec95fc66
423 2026-01-29 09:27:12.207997 192.168.62... 192.168.62.247 F1AP/NR RRC	SACK (Ack=44, Arwid=1048576) , DLRRCMessageTransfer, RRC Reconfiguration MAC=0x8f99e986
424 2026-01-29 09:27:12.242284 192.168.62... 192.168.62.247 F1AP/NR RRC	SACK (Ack=19, Arwid=1048576) , ULRRCMessageTransfer, RRC Reconfiguration Complete MAC=0xf8571e98
425 2026-01-29 09:27:12.242259 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0xa23d4654
429 2026-01-29 09:27:13.262025 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x3a154ac3
433 2026-01-29 09:27:14.282016 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x40ecfb7b
437 2026-01-29 09:27:15.301994 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x959ad52d
441 2026-01-29 09:27:16.321992 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x2963e2b4
447 2026-01-29 09:27:17.341978 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x60b8fdaa
453 2026-01-29 09:27:18.361968 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x303930c4
457 2026-01-29 09:27:19.381943 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0xe7ef2102
461 2026-01-29 09:27:20.401929 192.168.62... 192.168.62.247 F1AP/NR RRC	ULRRCMessageTransfer, Measurement Report MAC=0x4647a486

#5 - 2026-01-31 10:33 - 魏 幸幸

- 指派给 从 魏 幸幸 变更为 周 立伟

文件

屏幕截图 2026-01-31 103232.png

98 KB

2026-01-31

魏 幸幸