

3.0基站产品测试 - 错误 #5182

Rel_3.2.2_Pre1T1版本上行单流配置下鼎桥与星创易联cpe重建建立流程异常

2026-04-20 13:42 - 孙浩

状态:	进行中	开始日期:	2026-04-20
优先级:	一般	计划完成日期:	
指派给:	李宇哲	% 完成:	0%
类别:		预期时间:	0.00 小时
目标版本:		耗时:	0.00 小时
问题归属:	DU	目标解决问题版本:	Rel_3.2.2
发现问题版本:	Rel_3.2.2		

描述

【问题描述】Rel_3.2.2_Pre1T1版本上行单流配置下，鼎桥与星创易联cpe重建建立流程异常，手机重建建立流程正常；

```

RG_UE_REESTABLISH 1 uecfg[17019] reseetIdx[2]
ue_capability_info pres[0] pres[1] mimo_layers_ul[2]
RG_UE_REESTABLISH 2 msg4bo[17019]
RG_UE_REESTABLISH 3 msg4down[17019]
RG_UE_REESTABLISH 4 recfg_bo[17019]
RG_UE_REESTABLISH 5 recfg_down[17019]
pres[1] maxMimoLayersCbPusch[2] maxMimoLayersPdsch[4]
RG_UE_REESTABLISH 1 uecfg[17026] reseetIdx[9]
ue_capability_info pres[0] pres[1] mimo_layers_ul[2]
RG_UE_REESTABLISH 2 msg4bo[17026]
RG_UE_REESTABLISH 3 msg4down[17026]
RG_UE_REESTABLISH 4 recfg_bo[17026]
RG_UE_REESTABLISH 5 recfg_down[17026]
RLC DL UeCb is NULL in gUeCb, cellId=1, crnti=17024
RLC DL UeCb is NULL in gUeCb, cellId=1, crnti=17024
    
```

No.	Time	Source	Source port	Destination	Destination	Protocol	C-RNTI	Info	DU-UE
3736	10:48:00.718984	192.168.68.235	38472	192.168.68.235	38473	F1AP/NR RRC		DLRRCCMessageTransfer, RRC Release MAC=0x00000000	14
3740	10:48:01.052400	192.168.68.235	38473	192.168.68.235	38472	F1AP/NR RRC	17031	InitialULRRCCMessageTransfer, RRC Reestablishment Request	15
3741	10:48:01.053777	192.168.68.235	38472	192.168.68.235	38473	F1AP/NR RRC		DLRRCCMessageTransfer, RRC Reestablishment MAC=0x11344a04	15,14
3742	10:48:01.054881	192.168.68.235	38473	192.168.68.235	38472	F1AP		UEContextModificationRequired	15
3743	10:48:01.055604	192.168.68.235	38472	192.168.68.235	38473	F1AP		UEContextModificationConfirm	15
3744	10:48:01.081160	192.168.68.235	38473	192.168.68.235	38472	F1AP/NR RRC		ULRRCCMessageTransfer, RRC Reestablishment Complete MAC=0xeb5a35e6	15
3745	10:48:01.081919	192.168.68.235	38472	192.168.68.235	38473	F1AP/NR RRC		DLRRCCMessageTransfer, RRC Reconfiguration MAC=0xa4535f29	15
3757	10:48:01.906144	192.168.68.235	38473	192.168.68.235	38472	F1AP		UEContextReleaseRequest	15
3758	10:48:01.906448	192.168.68.235	38412	192.168.68.13	38412	NGAP		UEContextReleaseRequest	15
3759	10:48:01.913039	192.168.68.13	38412	192.168.68.235	38412	NGAP		UEContextReleaseCommand	15
3760	10:48:01.913263	192.168.68.235	38472	192.168.68.235	38473	F1AP/NR RRC		DLRRCCMessageTransfer, RRC Release MAC=0x4e22883e	15
3761	10:48:01.913307	192.168.68.235	38472	192.168.68.235	38473	F1AP		UEContextReleaseCommand	15
3763	10:48:01.913436	192.168.68.235	38473	192.168.68.235	38472	F1AP		UEContextReleaseComplete	15
3764	10:48:01.921039	192.168.68.235	38412	192.168.68.13	38412	NGAP		UEContextReleaseComplete	15

历史记录

#1 - 2026-04-23 10:45 - 李宇哲

- 状态从新建变更为进行中

文件

du界面打印.jpg	108 KB	2026-04-20	孙浩
鼎桥cpe重建建立流程异常.jpg	303 KB	2026-04-20	孙浩
3.2.2pre1T1版本鼎桥cpe重建建立异常-0420.rar	556 KB	2026-04-20	孙浩