

状态:	已关闭	开始日期:	2021-07-20
优先级:	普通	计划完成日期:	
指派给:	王 专	% 完成:	0%
类别:	gNB-PHY	预期时间:	0.00 小时
目标版本:		耗时:	0.00 小时
问题归属:	系统	FPGA板卡类型:	115P
发现问题版本:	Rel_2.1.8P	CPU类型:	
目标解决问题版本:	Rel_2.1.10P		
描述			
phydi_shutdown[from 18]: phyInstance: -1, sendStop: 0, testFileName: 0, phyIdStart: 0, phyIdStop: 1 [PHY_SHUTDOWN] PhyInstance⁰ PhyState¹ PhyStateCount¹ phydi_stop[from 18]: phyInstance: 0, sendStop: 0, phyIdStart: 0, phyIdStop: 1 PhyState¹ gnb_stop_fpga segv oops @ 0x7ff681422008 from core: 15 Segmentation Fault! info.si_signo = 11 info.si_errno = 0 info.si_code = 1 (SEGV_MAPERR) info.si_addr = 0x7ff681422008 Stack trace (non-dedicated): /root/yzmm/rel/GNB/phy/bin/l1app() [0x457261] /lib/x86_64-linux-gnu/libpthread.so.0(+0x11390) [0x7ff83810d390] /root/yzmm/rel/GNB/phy/libs/libnr.so.0(dm_schedule_fh_ul_descriptors+0x173) [0x7ff837328e1b] /root/yzmm/rel/GNB/phy/libs/libnr.so.0(drv_thread_function+0xf4c) [0x7ff83732a777] /lib/x86_64-linux-gnu/libpthread.so.0(+0x76ba) [0x7ff8381036ba] /lib/x86_64-linux-gnu/libc.so.6(clone+0x6d) [0x7ff8363ab41d] End of stack trace.Before dumping our Debug info sys_signal_segv:Processing SYS_SIG_TYPE_TERM begin stopping phy...phydi_stop[from 15]: phyInstance: -1, sendStop: 1, phyIdStart: 0, phyIdStop: 1 PhyState¹ PHY_STOP PhyInstance⁰ PhyState¹ PhyStartMode⁰ PhyStateCount¹ Send MSG_TYPE_PHY_STOP_RESP⁰ Func:PHY2DU_api_proc_send_api_list, phydi_query_state², PHY_STATE_START¹ After dumping our Debug info Received MSG_TYPE_PHY_SHUTDOWN_REQ: 0 DU2PHY_api_process_non_realtime Init⁰ Start⁰ Stop⁰ Shutdown¹ Dllq⁰ Ullq⁰ AddRemove[(nil)] Processing MSG_TYPE_PHY_SHUTDOWN_REQ: 0 phydi_shutdown[from 2]: phyInstance: 0, sendStop: 9, testFileName: 0, phyIdStart: 0, phyIdStop: 1 [PHY_SHUTDOWN] PhyInstance⁰ PhyState² PhyStateCount¹ [PHY_SHUTDOWN] phy_bbupool_deactivate_multicell ./run.sh: line 118: 2484 Segmentation fault (core dumped) /root/yzmm/rel/GNB/phy/bin/l1app table 0 1 --cfgfile=/root/yzmm/rel/GNB/phy/bin/physcfg.xml Cleanup after [PID] 2446 rm: cannot remove '/mnt/huge': Is a directory			
相关的问题:			
关联到 上行大带宽 - 错误 #580: 物理层出现FH 过来的slot号跳变导致物理层挂死		已解决	2021-06-28

历史记录

#1 - 2021-07-20 16:36 - 吕 国荣

- 关联到 错误 #580: 物理层出现FH 过来的slot号跳变导致物理层挂死 已添加

#2 - 2021-07-20 16:37 - 吕 国荣

基站启动后，立即出现物理层挂死，原因是出现tti的slot号和fh过来的slot对不上导致的。

#3 - 2021-08-04 18:23 - 吕国荣

- 状态从新建变更为进行中

#4 - 2022-08-03 04:50 - 高峰

- 指派给从吕国荣变更为王专

- 发现问题版本被设置为Rel_2.1.8P

- 目标解决问题版本被设置为Rel_2.1.10P

- FPGA板卡类型被设置为115P

- 问题归属系统已添加

此问题不知道是否外场环境温度还是进水导致

#5 - 2022-08-18 10:31 - 王专

- 状态从进行中变更为已解决

当前2.1.10P版本没有出现该问题。

#6 - 2022-08-24 04:24 - 高峰

- 状态从已解决变更为已关闭