

2.0基站产品化测试 - 错误 #1895

306_develop分支，XN切换崩溃

2024-06-25 09:29 - 杨 杨乐

状态:	已关闭	开始日期:	2024-06-25
优先级:	高	计划完成日期:	
指派给:		% 完成:	0%
类别:		预期时间:	0.00 小时
目标版本:		耗时:	4.00 小时
问题归属:	CU	FPGA板卡类型:	
发现问题版本:	Rel_2.1.15P	CPU类型:	
目标解决问题版本:	Rel_2.1.15P		
描述			
崩溃信息: warning: Unexpected size of section `reg-xstate/228532' in core file. #0 Glibc_free (mem=0x1) at malloc.c:2951 2951 malloc.c: No such file or directory. [Current thread is 1 (Thread 0x7f7f023de700 (LWP 228532))] (gdb) bt #0 GI_libc_free (mem=0x1) at malloc.c:2951 #1 0x000000000a2c8d6 in ngap::path_switch_request_acknowledge::~path_switch_request_acknowledge (this=<optimized out>, __in_chrg=<optimized out>) at /home/yl/cu/master/nr_hl_cu/cu/nr_hl_cu/ue_conn_mgr/build/../../common/include/../../ngap_codec/include/ngap_msg_types.h:4487 #2 gnb::conn_mgmt::process_path_switch_request_ack (this=<optimized out>, asn_msg=...) at /home/yl/cu/master/nr_hl_cu/cu/nr_hl_cu/ue_conn_mgr/build/../../src/ue_conn_mgr_ng_msg.cpp:510 #3 0x000000000a2e778 in gnb::conn_mgmt::process_ng_msg (this=this@entry=0x7f7f023d8c9f, cntrl_ref_id=..., ng_msg_type=<optimized out>, asn_msg=...) at /home/yl/cu/master/nr_hl_cu/cu/nr_hl_cu/ue_conn_mgr/build/../../src/ue_conn_mgr_ng_msg.cpp:714 #4 0x0000000009ff52c in gnb::ue_conn_mgr_msg_hdlr::process_sctp_user_msg_rx_ind (this=<optimized out>, sctp_user_msg_rx_ind=0x7f7ebc010e20) at /home/yl/cu/master/nr_hl_cu/cu/nr_hl_cu/ue_conn_mgr/build/../../src/ue_conn_mgr_msg_hdlr.cpp:85 #5 0x000000000bb3ae7 in gnb::ue_cntrl_thread::handle_sctp_user_msg_rx_ind_msg (this=0x2ee3a10, message=<optimized out>) at /home/yl/cu/master/nr_hl_cu/cu/nr_hl_cu/app/build/../../src/ue_cntrl_thread.cpp:104 #6 0x000000000bb34e4 in std::function<gnb::ret (ngp::message*)>::operator()(ngp::message*) const (_args#0=0x7f7ebc0008c0, this=0x7f7f023d8dc0) at /usr/include/c++/5/functional:2267 #7 gnb::ue_cntrl_thread::process_message (this=<optimized out>, message=0x7f7ebc0008c0) at /home/yl/cu/master/nr_hl_cu/cu/nr_hl_cu/app/build/../../src/ue_cntrl_thread.cpp:63 #8 0x00000000094ba46 in ngp::comm_thread::run (this=0x2ee3a10) at /home/yl/cu/master/nr_hl_cu/cu/nr_hl_cu/udp/build/../../ngp/include/ngp_comm_thread.h:286 #9 0x000000000d9dba7 in ngp::thread_entry_function (param=0x2ee3a10) at /home/yl/cu/master/nr_hl_cu/ngp/thread/build/../../src/ngp_sys_thread.cpp:112 #10 ngp::thread_start (param=0x2ee3a10) at /home/yl/cu/master/nr_hl_cu/ngp/thread/build/../../src/ngp_sys_thread.cpp:125 #11 0x00007f7f1f6916ba in start_thread (arg=0x7f7f023de700) at pthread_create.c:333 #12 0x00007f7f1f3c741d in clone () at ../sysdeps/unix/sysv/linux/x86_64/clone.S:109			

历史记录

- #1 - 2024-06-25 09:33 - 杨 杨乐
- 状态从 新建 变更为 进行中
- #2 - 2024-06-28 16:47 - 匿名用户
- 状态从 进行中 变更为 转测试
- 指派给从 匿名用户 变更为 孙 浩
- 测量XN切换是否正常
- #3 - 2024-06-29 09:09 - 孙 浩
- 指派给从 孙 浩 变更为 牛 兵桃

- #4 - 2024-07-12 10:05 - 牛兵桃
- 文件 40_1.pcap 已添加
 - 文件 70_1.pcap 已添加
 - 状态 从 转测试 变更为 已解决

切换功能正常，切换多次无挂死现象发生

- #5 - 2024-08-19 18:08 - 王旭初
- 状态 从 已解决 变更为 已关闭
 - 指派给 已删除 (牛兵桃)

文件			
70_1.pcap	212 KB	2024-07-12	牛兵桃
40_1.pcap	6.63 MB	2024-07-12	牛兵桃