基站横联 - 错误 #4211

onestep版本,自同步模式下,静态时隙的TB解不对

2025-10-09 09:59 - 高峰

状态:	新建	开始日期:	2025-10-09
优先级:	高	计划完成日期:	
指派给:	张倩	% 完成:	0%
类别:		预期时间:	0.00 小时
目标版本:		耗时:	0.00 小时
描述			

历史记录

#1 - 2025-10-09 10:00 - 高峰

son sniffer和dl sync触发情况下,tci可以解对,但tb都解不对

#2 - 2025-10-09 10:02 - 高峰

- 主题 从 onestep版本,自同步模式下,TB解不对 变更为 onestep版本,自同步模式下,静态时隙的TB解不对


#3 - 2025-10-10 12:24 - 高峰

- 1.上海自同步环境时域采数,有异常信号(181更明显,192有不明显);但仿真可以解对 2.需要PDS频域入口采数定位一下—— 赵强

#4 - 2025-10-10 15:53 - 赵强

- 文件img_v3_02qu_51cf946a-10ab-4a7e-a9eb-7084c65d84eg.jpg 已添加
- 文件img_v3_02qu_8f7f42b7-621c-4019-839f-079714b4948g.jpg 已添加
- 文件img_v3_02qu_5ee20b5d-49d5-41f0-bb2a-ebf28635b8dg.jpg 已添加
- 1、采频域数据,算法能够解对,但是星座图存在旋转。

2025-10-18 1/3



2、回灌UT也能解对

2025-10-18 2/3

```
[INFO]data process ue[0] symbol[12]
[INFO]MRC RENUM[192]
[INFO]EQ mrcRe[0] : 0x2C66E9D0
[INFO]EQ mrcRe[1] : 0xD3E71610
[INFO]EQ mrcRe[2] : 0x16172B82
[INFO]EQ mrcRe[3] : 0x2C21EB6D
[INFO]uci_cb_num[0] sch_cb_num[1] sch_proc_end[1]
[INFO]soft bit[7F]
[INFO] soft bit[AF]
[INFO]soft bit[7F]
[INFO]soft bit[47]
[INFO]NullLen[40] qm[2] cb E[3456] cb N[9600] rv[0] ldpc graph[2] zc[192] cb total num[1] cb valid bit[1880] cb origin lengt
[INFO]cb origin length OK[0] [0xD4]
[INFO]cb_origin_length_OK[1] [0xE8]
[INFO]cb_origin_length_OK[2] [0x1F]
[INFO]cb_origin_length_OK[3] [0x0]
[INFO]hh dl tb crc ok, state:0
[ERR]ZQ_OK_RNTI[0] nIdPusch[0] qamModOrder[0] mcsIndex[0] mcsTable[0] nrofLayers[0]
[ERR]rvIndex[0] harqProcessID[0] TBSize[0] ssb_rm_flag[0] SINR[129] [ERR]rbStart[0] rbSize[0] StartSymbolIndex[0] NrOfSymbols[0]
[ERR]DmrsScramblingId[0] DmrsIdentity[0] dmrsPorts[0] dmrsConfigType[0] nSCID[0] ulDmrsSymbPos[0]
[ERR]ZQ_OK_RNTI[0] nIdPusch[0] qamModOrder[0] mcsIndex[0] mcsTable[0] nrOfLayers[0]
[ERR]rvIndex[0] harqProcessID[0] TBSize[0] ssb_rm_flag[0] SINR[129] [ERR]rbStart[0] rbSize[0] StartSymbolIndex[0] NrofSymbols[0]
[ERR]DmrsScramblingId[0] DmrsIdentity[0] dmrsPorts[0] dmrsConfigType[0] nSCID[0] ulDmrsSymbPos[0]
[ERR]ZQ_PDSCH sfn[0] slot[10] rx_freqdata_ptr [0x106120a9] [0x43981ca5] [0xe01fffaa] [0x43981442]
[INFO]hl dl tb crc[0] : pdschTbSize[233] SINR[129]
[INFO]hl dl tb crc ok[0] : pdschTbSize[233] SINR[129]
```

#5 - 2025-10-11 19:21 - 高峰

符号间星座旋转,应该不是时偏问题,怀疑是相位补偿参数问题;如果时偏问题,应该时symbol内的旋转

#6 - 2025-10-16 18:27 - 高峰

定位到应该是PDS取到的agc异常;

agc 异常存在3个问题:

1. 事件deofdm 没有对agc赋值,需补充增加 msg fill函数

2.

agc初始化0,但在板看到有异常数据,有可能是DM空间pdcch_ctrl_ptr里面有随机数,拷贝到DDR的deofdm2_to_pdc1_msg_ptr时,随机数就覆盖到DDR中了;需要进一步确认

3. 事件deofdm 对这个地址nr_rx_deofdm2_to_pdc1_msg_addr,进行了2次赋值;一次是deofdm正常赋值,另外一次是deofdm2_trigger_pdcch1接口操作时重新赋了一次;属于bug。

文件

img_v3_02qu_51cf946a-10ab-4a7e-a9eb-7084c65d84eg.jpg	297 KB	2025-10-10	赵强
img_v3_02qu_8f7f42b7-621c-4019-839f-079714b4948g.jpg	411 KB	2025-10-10	赵强
img_v3_02qu_5ee20b5d-49d5-41f0-bb2a-ebf28635b8dg.jpg	337 KB	2025-10-10	赵强

2025-10-18 3/3