

B5G_UE - 错误 #5155

B5G DD口 T07__Alpha19版本3终端三角式环境双向ping包丢包率40%

2026-04-13 17:43 - 韩钰

状态:	进行中	开始日期:	2026-04-13
优先级:	高	计划完成日期:	
指派给:	宋承立	% 完成:	0%
类别:		预期时间:	0.00 小时
目标版本:		耗时:	0.00 小时

描述

B5G DD口 T07__Alpha19版本3终端三角式环境双向ping包丢包率40%

```
64 bytes from 192.168.80.3: icmp_seq=175 ttl=64 time=12.1 ms
64 bytes from 192.168.80.3: icmp_seq=176 ttl=64 time=10.1 ms
64 bytes from 192.168.80.3: icmp_seq=177 ttl=64 time=12.5 ms
64 bytes from 192.168.80.3: icmp_seq=178 ttl=64 time=11.5 ms
64 bytes from 192.168.80.3: icmp_seq=180 ttl=64 time=9.99 ms
64 bytes from 192.168.80.3: icmp_seq=182 ttl=64 time=9.99 ms
64 bytes from 192.168.80.3: icmp_seq=183 ttl=64 time=13.0 ms
64 bytes from 192.168.80.3: icmp_seq=184 ttl=64 time=9.96 ms
64 bytes from 192.168.80.3: icmp_seq=185 ttl=64 time=13.5 ms
64 bytes from 192.168.80.3: icmp_seq=187 ttl=64 time=9.91 ms
64 bytes from 192.168.80.3: icmp_seq=190 ttl=64 time=13.4 ms
64 bytes from 192.168.80.3: icmp_seq=191 ttl=64 time=9.96 ms
64 bytes from 192.168.80.3: icmp_seq=194 ttl=64 time=9.87 ms
64 bytes from 192.168.80.3: icmp_seq=196 ttl=64 time=10.1 ms
64 bytes from 192.168.80.3: icmp_seq=198 ttl=64 time=9.81 ms
64 bytes from 192.168.80.3: icmp_seq=199 ttl=64 time=14.3 ms
64 bytes from 192.168.80.3: icmp_seq=200 ttl=64 time=10.8 ms
64 bytes from 192.168.80.3: icmp_seq=201 ttl=64 time=14.9 ms
64 bytes from 192.168.80.3: icmp_seq=202 ttl=64 time=10.4 ms
^C
--- 192.168.80.3 ping statistics ---
202 packets transmitted, 117 received, 42.0792% packet loss, time 912ms
rtt min/avg/max/mdev = 6.622/11.428/15.024/1.685 ms
root@river:~#
```

```
msg_transfer_init is success !!!
handId0am 66048
[DEBUG]:core[0x000000c] send handshake request message,value[0x5a5a5a66].
ucp handshake is success!!!!
clkNode is :1.start to sync gpswill get gps sync status.
.....[DEBUG]:stc tracking ok !!!!! maintain g_sys_time:1776067495
sync_flag=1,set sync to cp
GPS sync ok;set tod incr_en
GPS sync ok;set sync to l2
.
gps sync ok.
Thread T2 priority: 0, policy:0, cpuid:5 sockId:0
Thread thread33 priority: 0, policy:0, cpuid:2 sockId:0
Thread T3 priority: 0, policy:0, cpuid:4 sockId:0
Thread T4 priority: 0, policy:0, cpuid:7 sockId:0
Thread T6 priority: 0, policy:0, cpuid:6 sockId:0
Thread T5 priority: 0, policy:0, cpuid:1 sockId:0
Thread ReceiveFromIc priority: 0, policy:0, cpuid:3
Rrc_Switch node type to DC-IE
FLOW_NC_2_SS_RRC_4_WN_NC_RRC_NBR_DEV_FIND_E
FLOW_NC_2_SS_RRC_4_WN_NC_RRC_NBR_DEV_FIND_E
logfile: /run/yz_zlog_20260413080842.log
[]
```

```
64 bytes from 192.168.80.1: icmp_seq=174 ttl=64 time=13.0 ms
64 bytes from 192.168.80.1: icmp_seq=175 ttl=64 time=17.0 ms
64 bytes from 192.168.80.1: icmp_seq=176 ttl=64 time=13.5 ms
64 bytes from 192.168.80.1: icmp_seq=177 ttl=64 time=17.3 ms
64 bytes from 192.168.80.1: icmp_seq=178 ttl=64 time=16.5 ms
64 bytes from 192.168.80.1: icmp_seq=179 ttl=64 time=12.9 ms
64 bytes from 192.168.80.1: icmp_seq=181 ttl=64 time=17.9 ms
64 bytes from 192.168.80.1: icmp_seq=183 ttl=64 time=17.5 ms
64 bytes from 192.168.80.1: icmp_seq=184 ttl=64 time=13.9 ms
64 bytes from 192.168.80.1: icmp_seq=185 ttl=64 time=17.9 ms
64 bytes from 192.168.80.1: icmp_seq=186 ttl=64 time=14.0 ms
64 bytes from 192.168.80.1: icmp_seq=189 ttl=64 time=14.8 ms
64 bytes from 192.168.80.1: icmp_seq=190 ttl=64 time=18.1 ms
64 bytes from 192.168.80.1: icmp_seq=191 ttl=64 time=15.3 ms
64 bytes from 192.168.80.1: icmp_seq=192 ttl=64 time=19.3 ms
64 bytes from 192.168.80.1: icmp_seq=193 ttl=64 time=15.8 ms
64 bytes from 192.168.80.1: icmp_seq=197 ttl=64 time=13.2 ms
64 bytes from 192.168.80.1: icmp_seq=201 ttl=64 time=14.6 ms
64 bytes from 192.168.80.1: icmp_seq=202 ttl=64 time=18.7 ms
^C
--- 192.168.80.1 ping statistics ---
202 packets transmitted, 119 received, 41.0891% packet loss, time 951ms
rtt min/avg/max/mdev = 12.623/15.950/26.072/1.149 ms
root@river:~#
```

历史记录

- #1 - 2026-04-13 17:50 - 李常
 - 状态从新建 变更为 进行中
 - 指派给从 李常 变更为 宋承立
- #2 - 2026-04-14 11:03 - 韩钰
 - 补充测试场景为um模式

文件

20260413-174250.jpg	604 KB	2026-04-13	韩钰
---------------------	--------	------------	----